# **Gina Parle**

**From:** Gina Parle on behalf of Peter Frampton

**Sent:** 01 May 2020 14:24

**To:** Emma.Pickernell@cheltenham.gov.uk

Cc: 'lan Kirby'

**Subject:** Application Ref: 16/00683/OUT - Oakhurst Rise, Cheltenham

Attachments: FLAC 38-1036 PLANNING SUBMISSION (ARBORICULTURE) - 43 UNIT SCHEME\_010520.pdf

Our ref: PJF/gp/PF/10093

Dear Emma

Town and Country Planning Act 1990 Application Ref: 16/00683/OUT Oakhurst Rise, Cheltenham

Thank you for your email earlier today [09.08] and the acknowledgement letter attached thereto. Please find attached a revised submission regarding arboriculture, which has been produced by the arboriculturist to confirm compliance with development plan policy on arboriculture.

# Kind regards

Peter J Frampton BSc (Hons), TP, MRICS, MRTPI

Attach: FLAC 38-1036 Planning Submission (Arboriculture) – 43 Unit Scheme 010520

CC: Ian Kirby



Oriel House 42 North Bar Banbury Oxfordshire OX16 OTH

Tel: 01295 672310 Fax: 01295 275606

Email: peter.frampton@framptons-planning.com

Our Office Manager, Natalie Dunkley, can be reached on 07803 452 910.

This email and any attachments are strictly confidential and are for the addressee only. Any forwarding, printing or disclosing the information may form a breach of confidence. Please contact the sender immediately if you have received this email in error. Normal Privacy and Copyright laws apply. Frampton Town Planning Limited has endeavoured to keep this email virus free and accepts no responsibility for any virus attached thereafter.



Principal Consultant:
Julian Forbes-Laird
BA(Hons), Dip.GR.Stud, MICFor, MRICS, MEWI, Dip.Arb.(RFS)



# **OAKHURST RISE**



# PLANNING SUBMISSION (ARBORICULTURE)



43 Unit Scheme

- TREE SURVEY TO BS5837:2012
- PROPOSED TREE RETENTION & REMOVAL
- TREE PROTECTION PLAN

Prepared for: William Morrison (Cheltenham) Ltd

FLAC Instruction ref: SC38-1036

Issued: April 2020

Operations Director, Planning & Development
Patrick Stileman
BSc(Hons), MICFor, MRICS, RC.Arbor.A, CUEW, Dip.Arb(RFS)

Senior Associate Director
Ben Abbatt
BA(Hons), MICFor, MRICS, RC.Arbor.A, CEnv, Dip.Arb(RFS)

Dendron House
Barford Road • Blunham
Bedford • MK44 3ND
T 44 (0)1767 641648
F 44 (0)1767 660330
E enquiries@flac.uk.com
www.flac.uk.com



# FLAC Instruction ref. CC38-1036 OAKHURST RISE

Outline application for residential development of 43 dwellings – access, layout and scale not reserved for subsequent approval

# <u>Arboricultural planning submission</u>

# Introduction

FLAC remains instructed by William Morrison (Cheltenham) Ltd in the promotion of land off Oakhurst Rise, Cheltenham. The current proposals are for a total of 43 residential units.

These proposals have been developed in light of the Inspector's Decision on Appeal Ref. 3227293, and in light of National and Local Planning Policy, emerging Local Policy HD4 *Land off Oakhurst Rise*, and a Tree Preservation Order.

# The Appeal Decision

The following matters arising from the Appeal Decision have been addressed in full in the design of the current proposals:

- 1. Retention of tree 3014 (TPO tree T11)
- 2. Removal of all construction from veteran tree buffer zones
- 3. Removal of all gardens from within veteran tree buffer zones

Given the Inspector's endorsement of the RAVEN method for identification of ancient, veteran and notable trees, the list of which trees qualify under these headings remains unchanged.

# National Planning Policy

Paragraph 175c of the NPPF is relevant insofar as there are irreplaceable habitat trees present.

All such trees would be retained, and would be afforded protective buffer zones in line with Natural England and Forestry Commission advice.

Accordingly, the proposals are compliant with National Planning Policy.

# Local planning policy

So far as is presently material, local planning policy comprises Local Plan 2006 Saved Policies G12, G13 and GE6, and Joint Core Strategy Policy 2017 Policy SD9.



# Saved Policy GE6 - Trees and Development

# POLICY GE 6

# TREES AND DEVELOPMENT

Objective O12

Development which would cause permanent damage to trees of high value (note 1) will not be permitted.

The following may be required in conjunction with development:

- (a) the retention of existing trees; and
- (b) the planting of new trees (note 3); and
- (c) measures adequate to ensure the protection of trees during construction works.

#### Note 1

'High value' means a sound and healthy tree with at least 10 years of life remaining which makes a significant contribution to the character or appearance of a site or locality

# Note 2

The preservation and planting of trees in conjunction with development should take account of the guidance in British Standard 5837: 2005.

#### Note 3

Where appropriate the Council will seek agreement from developers for the planting of new trees offsite.

### Note 4

See also policy CP 3 (sustainable environment).

In relation to the three possible requirements identified within Policy GE6:

- a) As set out on the Tree Survey & Retention Plan, 100% of the high quality trees present are proposed for retention, as well as 85% of those of moderate quality
- b) Accompanying landscape proposals confirm that numerous new trees would be delivered as part of the proposals
- c) The Tree Protection Plan provides safeguarding details for retained trees

Accordingly, the proposals comply with this Policy.

# JCS Policy SD9 - Biodiversity and Geodiversity

Clause 6 of JCS Policy SD9 seeks inter alia to avoid harm to biodiversity through on-site mitigation where possible. In the present case, there is a *theoretical* risk of harm to biodiversity from adverse impacts on ancient and other veteran trees and accordingly SD9 is engaged.

However, mitigation for this theoretical risk is provided on site in the form of buffer-zones in accordance with NE/ FC recommendation, such that no harm would in fact arise.

The result is that the proposals comply with this Policy also.



# Other material considerations

# **Emerging Local Policy**

Three Policies of the Emerging Local Plan (awaiting Adoption) are also relevant:

**Policy HD4**, Land off Oakhurst Rise, requires inter alia the protection and long-term maintenance of mature trees and hedges.

The Tree Protection Plan provides details for the protection during development of all retained trees and hedges. It also includes an *Outline Arboricultural Management Plan*.

Further details as regards forward management of trees and hedges could be sought via a planning condition should the Council consider these to be required.

It follows that the proposals are compliant with this Emerging Policy.

**Policy G12**, *Protection and Replacement of Trees*, seeks to avoid unnecessary felling of trees on private land and notes that the Council will make trees subject to Tree Preservation Order where appropriate.

It is apparent from the wording of Policy G12 that it relates to preservation of trees other than within the planning and the development context. It is therefore not required that the current proposals are in compliance with this policy, providing that they are in compliance with Policy G13 (below) and HD4.

**Policy G13**, *Trees and Development*, seeks to avoid permanent damage to trees with anything more than 10 years remaining life expectancy, which make a *significant contribution to the character or appearance of a site or locality*, i.e. trees described by the Policy as being of "high value" (Note 1). At Note 2, it is required that existing trees shall be considered in light of BS5837:2012 *Trees in Relation to Design, Demolition and Construction - Recommendations*, which identifies "high value" trees as those placed by the tree survey into the A category.

The proposals provide for the retention of all high value trees as defined in BS5837:2012 and are therefore Policy-compliant in this respect.

This Policy states that the Council may also require the planting of new trees and measures adequate to ensure the protection of trees during construction works. The former would be delivered in abundance by the proposals at hand, whilst the latter are apparent from the Tree Protection Plan within this submission material.

Accordingly, the proposals are Policy-compliant in these respects also.



# The Cheltenham Borough Council Tree Preservation Order 1/1981 Whitefriars School

This Tree Preservation Order protects a number of the existing trees on the site. All such trees would be retained.

# Matter for resolution by planning condition

One matter is required for resolution by planning condition: the Root Protection Area for tree 3015 would be subject to a small incursion of 25m<sup>2</sup> for the construction of vehicular access to northwest.

In recognition of this, the Tree Protection Plan provides for an increase in protection to northeast of 50m<sup>2</sup>. In our view, the incursion would not result in a material adverse impact on the tree and accordingly is acceptable. If, however, the Council would prefer the vehicular access to be constructed according to a no-dig specification, this can readily be accommodated. Outline details for a suitable specification are provided on the accompanying Tree Protection Plan, under the heading *Tree Protection Measures for New Permanent Hard Surfacing Over RPAs*.

The Council is invited to take a view on this point and apply a conditioned requirement for the no-dig specification, should it be minded to do so, as part of conditioned tree protection.

In this regard, attention is drawn to our recommendations on the Tree Protection Plan for installation of drainage in proximity to trees: we consider that making use of the recommended details a requirement of the anticipated tree protection condition is advisable.

# Overall conclusion on Local and Emerging Policy

It is our analysis of each of the relevant Policies discussed above that the 43 Unit Scheme is compliant in each case. Accordingly, we consider that there are no policy-based grounds why planning permission should be withheld.

# Contents

This planning submission comprises the following elements:

- Tree survey compliant to BS5837:2012, supported by a detailed explanatory key
- RAVEN: methodology and findings
- Tree Survey, Retention and Removal Plan (FLAC dwg no. TSRP 38-1036.02-B)
- Tree Protection Plan (FLAC dwg no. TPP 38-1036.03-D)

Forbes-Laird Arboricultural Consultancy Ltd



# OAKHURST RISE: KEY TO TREE SURVEY DATA SCHEDULE

# Note

This survey has been undertaken in compliance with BS5837:2012; it is not intended to be a tree safety survey. Any notes offered on structural integrity of trees are incidental, though where trees are considered to be in immediately hazardous condition (identified by red font in the *Structural condition & Notes* column, see below), our recommendations given for immediate intervention should be put in hand by the owner / site manager as soon as can be arranged.

Trees are dynamic living organisms capable of achieving considerable size and structural complexity. They are exposed to and can become damaged by the elements and by human activity, and have co-evolved with decay-causing organisms that can degrade and sometimes destroy their structural integrity. Due to genetic characteristics and local microenvironmental factors this integrity can be innately uncertain. The laws and forces of nature dictate a natural failure rate even among trees that are healthy and structurally sound. By their very nature, therefore, trees cannot be considered entirely hazard-free.

Tree surveys and / or tree inspections are, inherently, only a snapshot in time of the physiological and structural condition of the trees concerned.

Unless otherwise stated in our reporting material, all such surveys and inspections are undertaken from ground level and no internal inspections or tests have been undertaken. Any structural defects present might be not be visible, for example being masked by vegetation, whether the tree's foliage, plants growing round the base of the tree, or climbing plants growing on the stem and into the crown.

Unless otherwise states, the survey data should be considered time-limited **for planning purposes** to a maximum of three years (absent revisions of BS5837, which render pre-existing data obsolete).

# FLAC Ref. No.

Tree numbers per FLAC dwg no. 38-1036.01 and subsequent drawings

In line with the advice of BS5837:2012, where trees occur as a cohesive group feature (prefixed TG for tree group or WG for woodland group), they are assessed as such

Size data for TG or WG are given as mean figures for trees at roughly the 80 percentile of the population concerned. Trees in the 90-100 percentile range for the group are identified on the TSP

Trees within TG/ WG boundaries that have more than one stem and which are sub-dominant within the TG/ WG (i.e. <80 percentile) are subsumed within the TG/ WG data; dominant multi-stemmed trees (i.e. >80 percentile) within TG/ WG boundaries are listed as individual trees

TG/ WG outlines follow the mapping base (typically either topographical survey or geo-rectified aerial imagery)

Hedges (domestic) are recorded prefixed H and are always excluded from the provisions of the Hedgerows Regulations 1997

Hedgerows (rural) are recorded prefixed HR and possibly fall within the provisions of the Hedgerows Regulations 1997

All numbering starts from x001 for each type of vegetation, where x identifies the surveyor (9000 series = JFL). Thus:

9000 Individual tree
TG9000 Tree group
WG9000 Woodland group
H9000 Domestic hedge
HR9000 Rural hedgerow

The addition of the FLAC instruction ref. ahead of the tree number provides a unique, non-repeated reference number for the arboricultural feature in question

Any trees omitted from the topo survey are listed on the referenced plan, though their positions are only shown indicatively. Off-site trees are included where deemed relevant, though their positions are also shown indicatively if omitted from the topo base

# TPO Ref.

Statutory protection listing for individual trees, TG and WG

ATTENTION: SEE NOTE IMMEDIATELY BELOW

# Note

This column is only completed in cases where FLAC has been instructed to undertake a TPO search and correlation to FLAC reference numbers. The absence of data in this column <u>must not</u> be taken to indicate that the trees concerned are not under TPO protection. Statutory protection may also arise from the trees' location within a Conservation Area. Further statutory control over tree removal may be conferred by the Forestry Act 1967

# **Species**

Tree species as listed in the schedule by common name. Species present are:

Common name	Botanical name	Provenance	Notes
Ash	Fraxinus excelsior	Native	
Blackthorn	Prunus spinosa	Native	
Blue Atlas cedar	Cedrus atlantica 'Glauca'	Exotic	
Cherry laurel	Prunus laurocerasus	Exotic	
Crimean pine	Pinus nigra subsp. pallasiana	Exotic	
Damson	Prunus domestica subsp. insititia	Native	
Elder	Sambucus nigra	Native	
Elm	Ulmus procera	Native	
Field maple	Acer campestre	Native	
Hawthorn	Crataegus monogyna	Native	
Hazel	Corylus avellana	Native	
Holly	llex aquifolium	Native	
Holm oak	Quercus ilex	Exotic	
Lawson cypress	Chamaecyparis lawsoniana	Exotic	
Leyland cypress	x Cupressocyparis leylandii	Exotic	
Norway spruce	Picea abies	Exotic	
Pedunculate oak	Quercus robur	Native	
Red horse chestnut	Aesculus x carnea	Exotic	
Scots pine	Pinus sylvestris	Native	
Sycamore	Acer pseudoplatanus	Naturalised	

# **Tree Count**

For trees assessed as groups (ident. prefix TG), number of trees present, according to:

2-10 trees Accurate count 11-50 trees Close estimate 51-100 trees Estimate

# Area m<sup>2</sup>

For trees assessed as woodland (ident. prefix WG), existing area in square metres within survey envelope, derived from CAD interrogation of the completed tree survey plan

# Ht. (m)

Tree height in metres

Either:

# **Crown Spread**

For individual trees, measured radial crown spread in metres, listed for each of the four cardinal points

Or:

# **MRCS**

For trees assessed as groups or woodland, an estimated mean radial crown spread in metres for trees at the 80 percentile size

# Note

For trees assessed as woodland, sample measurements for canopy overhang beyond woodland boundary (i.e. hedgerow, fence, ditch etc.) are given on the tree survey plan

Or:

# Mean Width

Mean width in metres of hedge or hedgerow

# **Length**

Approximate length in metres of hedge or hedgerow

# Ht. 1st Br.

For individual trees and trees assessed as groups or woodland, height in metres above ground of attachment point of first significant branch (cardinal point may be given indicating growing direction)

# Ht. Can.

For individual trees and trees assessed as groups or woodland, mean height in metres of lower extent of tree canopy above ground

# **Stem Count**

For individual trees, number of stems present below 1.5m AGL. Stem count affects diameter entry as follows:

Where the stem count is 1 the diameter should be entered into the 1 column under Stem Dia.

Where the stem count is up to 5 each stem dia. should be listed

Where the stem count exceeds 5, the mean stem diameter should be entered in the 1 column

Either:

# Stem Dia. (mm)

Stem diameter(s) at 1.5m above ground level (see measurement system in BS5837:2012 Annex C), given in millimetres

Where entered 1:

Single measured stem diameter

Where entered 2-5:

Multiple measured stem diameters, listed per stem

Where entered >5:

For trees with more than five stems, diameter is listed as an estimated mean

Where the diameter entry for trees with 1 or 2-5 stems appears in italics, this indicates that it was estimated by the surveyor (for example, due to the presence of ivy on the stem)

It is our practice to round up when estimating stem diameters

Or:

# Specimen Stem Dia.

For trees assessed as groups or woodland, stem diameter in millimetres at 1.5m above ground level for 80 percentile member of TG or WG. Trees with larger diameters are identified on the TSP

Or:

# Mean Stem Dia.

Mean stem diameter in millimetres above the basal flare of hedge or hedgerow component plants

Either:

# **RPA Rad.**

Radius in metres of the notionally circular Root Protection Area

Or:

# Specimen RPA Rad.

For trees assessed as groups or woodland, radius in metres of the notionally circular Root Protection Area based on specimen diameter for TG or WG 80 percentile tree

Either:

# **RPA Area**

Conversion of RPA radius to an area, given in m<sup>2</sup>, capped to a maximum of 707m<sup>2</sup> (in line with BS5837:2012)

Or:

# Specimen RPA Area

For trees assessed as groups or woodland, conversion of specimen RPA radius to an area, given in m<sup>2</sup>, capped to a maximum of 707m<sup>2</sup>

# Note

RPA for hedges or hedgerows is to be taken as 3m from the centreline, half the height or 2m beyond existing width, whichever is the greater

# **Life Stage**

Life stage assessment according into:

Y Young
SM Semi-mature
EM Early mature
M Mature
OM Over-mature

# **Phys. Condition**

An assessment of the physiological condition (i.e. health/vitality) status of the tree summarised according to:

**G**OOD Generally in healthy condition

**F**AIR Condition satisfactory though below mean species performance

**P**OOR Tree in decline/retrenching

**D**EAD Self explanatory

# **Structural condition & Notes**

Notes on the apparent structural integrity of the tree based on visual tree assessment, including notes on form, taper, forking habit, storm damage, decay fungi, pests, etc. plus other pertinent observations

# **Management recommendations**

Preliminary recommendations for intervention (e.g. tree surgery, felling, etc) in relation to existing context

Trees assessed as being in apparently immediately hazardous condition will be notified to the client separately as soon as practical. Where the recommendation is for further investigation, including removal of ivy and reinspection, the given retention span and quality/value grade (see below) should be treated as provisional

# **Notes**

This is **not** intended to comprise a specification for tree work: further advice should be sought prior to implementation

Change in land use (target value) requires further assessment

# Ret. Span

Estimated remaining retention span based on species, condition & context divided into the following bands (relates to quality and value grade achievable as stated):

Years	Best QV grade
<10	U
10+	С
20+	В
>40	Α

# **QV Grade**

Quality & Value grade classification according to BS5837:2012 (see attached extract from BS5837:2012 'Table 1 - Cascade Chart for Tree Quality Assessment') –

Grade	Summary meaning	Ident. colour spot on TSP
U	Trees that are unretainable in viable condition	Dark red
Α	High quality & value and consequent high retention priority	Light green
В	Moderate quality and value (moderate priority for retention)	Mid-blue
С	Low quality and value (generally considered to be sacrificial)	Grey

# Note

Trees present which we consider to be exceptional specimens are identified by the suffix \* after the A grade, e.g. A1\*

# **Proposal**

This column identifies:

- 1. Pre-planning (Arboricultural Stages 1, Tree Survey, & 2, Design): JFL's initial view of a defensible tree retention / removal balance
- Planning submission (Arboricultural Stage 3):
   The actual tree retention / removal balance as proposed

The following codes are used:

KEI	Trees that would be retained
PRET	For tree groups (TG), woodlands (WG) & hedgerows (HR) – signifies partial retention (see below)
REM	<ol> <li>Trees defensibly removed to facilitate development</li> <li>Trees that would be removed</li> </ol>
U	Trees identified to be unsuitable for retention

# No. of trees retained

For tree groups only

Number of trees retained out of the total recorded for the group. Outcomes are as follows:

Survey grade U Number of trees for retention defaults to 0 (can be amended by manual override)

Proposal code RET Number of trees for retention defaults to total from *Tree Count* data field

Proposal code PRET No. of trees for retention requires manual input following interrogation of relevant plans

Proposal code REM Number of trees for retention defaults to 0

# **Trees retained %**

For tree groups only

Percentage of pre-existing TG tree count that would be retained, based on an auto-sum derived from inputs into the preceding column

# Area retained m<sup>2</sup>

For woodlands only

Area, in square metres, of woodland (WG) proposed for retention. Outcomes are as follows:

Survey grade U Area for retention defaults to 0 (can be amended by manual override)

Proposal code RET Area for retention defaults to existing area

Proposal code PRET Area for retention requires manual input following interrogation of relevant plans

Proposal code REM Area for retention defaults to 0

# Area retained %

For woodlands only

Percentage of pre-existing WG area that would be retained, based on an auto-sum derived from inputs into the preceding column

# Length retained m

For hedgerows only

Length, in metres, of hedgerow (HR) proposed for retention. Outcomes are as follows:

Survey grade U Length for retention defaults to 0 (can be amended by manual override)

Proposal code RET Length for retention defaults to existing length

Proposal code PRET Length for retention requires manual input following interrogation of relevant plans

Proposal code REM Length for retention defaults to 0

# **Length retained %**

For hedgerows only

Percentage of pre-existing HR length that would be retained, based on an auto-sum derived from inputs into the preceding column

Category and definition	Criteria (including subcategories where appropriate	e)		Identification on plan							
Trees unsuitable for retention (see Not	e)										
Category U Those in such a condition that they cannot realistically be retained as living trees in the context of the current land use for longer than 10 years											
	1 Mainly arboricultural qualities	2 Mainly landscape qualities	3 Mainly cultural values, including conservation								
Trees to be considered for retention											
Category A Trees of high quality with an estimated remaining life expectancy of at least 40 years	Trees that are particularly good examples of their species, especially if rare or unusual; or those that are essential components of groups or formal or semi-formal arboricultural features (e.g. the dominant and/or principal trees within an avenue)	Trees, groups or woodlands of particular visual importance as arboricultural and/or landscape features	Trees, groups or woodlands of significant conservation, historical, commemorative or other value (e.g. veteran trees or wood-pasture)								
Category B Trees of moderate quality with an estimated remaining life expectancy of at least 20 years	Trees that might be included in category A, but are downgraded because of impaired condition (e.g. presence of significant though remediable defects, including unsympathetic past management and storm damage), such that they are unlikely to be suitable for retention for beyond 40 years; or trees lacking the special quality necessary to merit the category A designation	Trees present in numbers, usually growing as groups or woodlands, such that they attract a higher collective rating than they might as individuals; or trees occurring as collectives but situated so as to make little visual contribution to the wider locality	cultural value								
Category C Trees of low quality with an estimated remaining life expectancy of at least 10 years, or young trees with a stem	Unremarkable trees of very limited merit or such impaired condition that they do not qualify in higher categories	Trees present in groups or woodlands, but without this r conferring on them significantly greater collective landscape value; and/or trees offering low or only temporary/transient landscape benefits	Trees with no material conservation or other cultural value								

# **FLAC Note**

diameter below 150 mm

The original contents of the column *Identification on plan* have been replaced by FLAC in the version above; spot colours to RGB codes given in BS5837:2012 Table 2

# Data for individual trees

FLAC Ref. No.	1981 TPO Ref	Species	Ht.	Crown	Sprea	<b>d</b> (m)	Ht. 1 <sup>st</sup> Br.		Stem Count		Stem	Dia. (m	nm)		RPA Rad.	RPA Area	Life Stage	Phys. Conditio	Structural condition & Notes Management recommendations F	Ret. Span	QV Grade	Proposal
			(m)	N S	v	v	<b>E</b> (m)	(m)		1/ mean	2	3	4	5	(m)	(m2)	Y-SM-EM-M- OM	G-F-P-D	<	10, 10+ 20+, >40	U-A-B-C	
3001		Ash	14.4	4.5	4	4.5	2.6 2 NW	2.5	1	257					3.09	30	EM	F	Upright stem. Principal branch structure and unions in satisfactory condition. Some crown asymmetry after companion shelter at east. Tree of relatively low significance.	>40	C1	RET
3002	T5	Pedunculate oak	24	8.5	11	9.3	9.6 3.8 W	1	1	1370					15.00	707	М	G	Very stout upright stem. Principal branch structure and unions in satisfactory condition.  Bird box at 2 metres north. High quality landscape tree.	>40	A1	RET
3003		Hawthorn	3.5	3.2	2	4.5	1 1 W	0	1	180					2.16	15	EM	F	Scrubby specimen leans heavily over to north-west. Tree of relatively low significance. No action required at time of survey.	10+	C1	RET
3004	Т6	Ash	9.5	5 4	l.3	5.7	1 2.8 W	3	1	780					9.36	275	М	F	Significant basal decay and severe degradation of root buttress at west. Extensive bark loss around stem at west side. Large Inonotus hispidus fruiting bracket on stem at 4.5 metres west in zone of bark damage. Very heavily reduced but now unsightly. Very poor overall condition.	<10	U	U
3005	T8	Crimean pine	20	10.5	2	9.3	2 4 E	8	1	910					10.92	374	М	G	Stem has a slight incline to north from ground level. Large limb from 4 metres east has an area of bark wounding on upper side of limb near union with stem, advise pruning to mitigate. Large scaffold limb at west has a sub-optimal union. Upper western crown contains partially fractured branches with some that have fallen to ground level.  Prune out broken/hanging branches at upper west crown and reduce branch structure associated with the western scaffold limb by 2 metres to mitigate for sub-optimal union with stem. Prune branch extents of large low limb from 4 metres east by 2 metres to mitigate potential weakening at wound near stem.	20+	B1	RET
3006		Sycamore	5	1.5 2	1.3	2	2.8 1.2 S	1	2	130	60				1.72	9	SM	F	Small, scrubby twin-stemmed specimen close to boundary. Low arboricultural or landscape merit.  No action required at time of survey.	20+	C1	RET
3007	Т9	Pedunculate oak	9.6	5	5	5	5.5 3 W	2.5	1	1450					15.00	707	EM	G	Veteran, relic tree. Very stout lower stem with extensive stem hollowing, cavity opening at north side reveals very large cavity providing various habitat spaces. Old, small but tough fruiting body on north side of stem at 1.5 metres, provisionally identified as either <i>Phellinus robustus</i> or extinct <i>Ganoderma</i> species. Large wound on stem at 2 metres after scaffold limb loss. Crown retrenchment extensive, now only a 3.5 metres tall stem section bearing three remnant scaffold member stubs. Dead and non-functional volumes of dead wood present within scaffold stubs providing opportunities for water pooling plus additional habitat spaces. Foliage bearing crown comprises a small number of branches on each scaffold stub adapted now as a consolidated secondary crown and in good overall vitality.	>40	A3	RET
3008	G3	Pedunculate oak	18	12.4	4	7	8 3.5 N	1	1	1130					13.56	577	М	G	Stout lower stem. Slight stem incline to south. Principal branch structure and unions in satisfactory condition. Significant crown bias to south. Good overall condition. Small pond immediately to south of stem, wet at time of survey.	>40	A1	RET
3009	G3	Pedunculate oak	14	4.5 10	).5	6	7 4 S	1	1	760					9.12	261	М	G	Stem and principal branch structure and unions in satisfactory condition. Rather asymmetrical crown form due to suppression by companion trees to eat and west. Ivy impedes inspection. Satisfactory overall condition.	>40	B1	RET
3010	G3	Pedunculate oak	14	6.5 €	i.5	8	7 2 NW	1	1	930					11.16	391	М	F	Fistulina hepatica fruiting body on root buttress at ground level east. Laetiporus sulphureus on old branch loss wound at 2 metres south. Numerous habitat holes within branch structure indicating heartwood fungal decay is well progressed. General bias of crown structure to west. Some distal crown dieback but chiefly small diameter material. Physiological condition and vitality coupled with structural condition considered likely to limit long-term retention prospects such that th specimen is not likely to have sufficinet longevity for veteran status. Crown consolidation advised to stabilize decayed structure in the short-term.	>40	B1	RET
3011		Ash	11.5	3.5 2	2.5	2	2.7 1.5 N	1.8	1	255					3.06	29	EM	Р	Upright stem and structural habit. Severe decline through crown.  Fell.	<10	U	U
3012		Ash	12	5 3	3.5	3	4 2.5 E	1	2	320	290				5.19	85	EM	F	Twin stems from close to ground level. South stem bifurcates at 2 metres with dead western scaffold member. Bark damage and loss of north stem, further decline expected. Limited potential.	10+	C1	REM
3013		Ash	12	6	6	6	5.5 2.5 W	1	3	360	320	220			6.36	127	EM	F	Multi-stemmed from ground level. Sub-optimal bark included unions developing between stems. Asymmetrical crown due to companion shelter at north. Tree of relatively low significance.  No action required at time of survey.	20+	C1	REM
3014	T11	Pedunculate oak	11	6.5 5	i.2	6.5	6.5 1.6 W	1	1	980					11.76	434	ОМ	F	Bark wounding after historic lightning strike seen as broad tongue of bark loss from ground level south extending into upper crown structure, exposed and desiccated non-functional heartwood within affected stem section comprises large volume dead wood.  Scattered dead wood and smaller distal decline. Crown consolidated by pruning/tidying probably subsequent to past storm damage.	>40	В3	RET
3015	T10	Pedunculate oak	16.7		5	9	14.8 2 S	1	1	1460					15.00			G	Very stout lower stem. Broadly spreading crown structure. Crown bias to east. Dense ivy to 6 metres. Low limb to north shows adaptive growth at longitudinal fracture approximately 5 metres from the stem, pruning advised to stabilize. Few large dead limbs scattered through crown.  Stem and principal branch structure and unions in satisfactory condition. Some crown	>40	A1	RET
3016 3017		Ash Sycamore	14.5	5.5	4	6.5	8 2.5 W 5 2 W	1.2	1	690 500					6.00	215		G F	asymmetry after companion shelter. Satisfactory overall condition.  Stem and principal branch structure and unions in satisfactory condition. Some crown asymmetry after companion shelter to south. Satisfactory overall condition.  No action required at time of survey.  No action required at time of survey.	>40	B1 B1	REM

FLAC Ref.	1981 TPC	Species	Ht.		Crowi	n Sprea	ad (m)	)	-		Stem Count		Stem	Dia. (mm	)	RPA Rad	. RPA Ar	ea Life St	age i	Phys.	Structural condition & Notes Management recommendations	Ret. Span	QV Grade	Proposal
140.	Kei		(m)		N S	١	w			(m)		1/ nean	2	3	4 5	(m)	(m2)	Y-SM-EN	√-M-	G-F-P-D		<10, 10+ 20+, >40	U-A-B-C	
3018	T18	Pedunculate oak	22.	5	7.5 1	0.5	11.3	9.5 3	S	2		1760				15.0	0 7	07 M		G	Veteran tree. Very stout lower stem to bole and multiple regrown scaffold members after cessation of historic pollard management. Extensive stem and bole hollowing at east associated with major limb loss in the presence of brown rot decay fungi Fistulina hepatica. Failure of large scaffold member at north-east scaffold member leaves a large dead wood resource containing habitat spaces and including Laetiporus sulphureus fruiting body and exposed heartwood. Additional F. hepatica fruiting body also present on old branch breakout wound on central scaffold member at north.  Several wounds and associated habitat space features through structure. Range of dead wood sizes. Crown retrenchment via storm damage as described but otherwise bearing a fully regrown crown in good overall vitality.	>40	A3	RET
3019		Ash	10	6	3	8	5	3.3 4	S	4	1	560				6.7	2 1	42 M		F	Stem inclined slightly to south. Severe bark loss at north obscured by surrounding debris, probably associated with infection by <i>Armillaria</i> species. Physiological impacts of infection and damage seen as thinning to branch structure, expected to deteriorate further.	10+	C1	RET
3020		Ash	14	4	5.5	4	5	5 3	Е	2	2	380	380			6.4	5 1	31 M		F	Twin stems from ground level with bark-included union developing. Past limb removals at north. Suppressed and unremarkable specimen.	20+	C1	RET
3021		Ash	1(	0	7	5 :	11.1	8.5 2	S	0	1	1520				15.0	7 00 7	07 M		F	Veteran tree. An extensively hollow and decayed lower stem section with only a relatively thin residual wall of functional wood after decay of the large majority of the heartwood volume. A cavity opening to north side of the stem occupies the length of the remnant stem section. Crown comprises only later/recent adventitious shoots that have now become the principal limbs after past loss of all primary crown structure and is in good physiological condition so pruning is advised of this later material to manage both the weight and sail area acting upon the increasingly fragile residual stem wood.  NB currently the crown is not excessively suppressed by the surrounding younger and more vigorous trees, shading out should be avoided e.g. by pruning of the ash so that it is marginalized relative to the younger trees or by allowing younger trees to overtop the ash. Remaining dysfunctional wood within the central column of the stem is riddled by insect galleries. Fungal degradation of heartwood displays a pattern consistent with cubical brown rot mode. Varied habitat spaces present and mostly within the stem.	>40	A3	RET
3022	T16	Pedunculate oak	2:	3	9.5	11	12.3	11.5 5	E	1.5	1	1205				14.4	6 6	57 M		G	A stout, upright stem with good taper. Principal branch structure and unions in good condition. Attractive, broadly spreading crown structure. High quality landscape tree with good potential.  No action required at time of survey.	>40	A1	RET
3023	A4	Pedunculate oak	24	4	12 1	2.5	5.5	10 5.	.5 S	2	1	1365				15.0	0 7	07 M		G	Very stout upright stem. Multiple limb failures from north crown, possibly due to high wind events, residual limbs potentially exposed and vulnerable to similar failures by loss of crown integrity. Intervention pruning at remainder of north crown may prevent further crown failures.  Reduce remainder of north crown by 2.5 metres to stabilize due to apparent vulnerability to large limb failures.	>40	A1	RET
3024	A4	Pedunculate oak	2:	2	10	6	5.5	6.5 9	S	9	1	1110				13.3	2 5	57 M		G	Stout upright stem. Principal branch structure and unions in satisfactory condition.  Recent pruning management of west crown in the interests of maintenance of the relationship to the proximal dwelling to west. Bird box at 3 metres north. Good overall condition.  No action required at time of survey.	>40	A1	RET
3025	T15	Pedunculate oak	1:	8 :	10.5	9	3	7 3.	5 N	3	1	1462				15.0	0 7	07 M		F	Very stout lower stem with large scaffold member sweeping up into crown from 3 metres south and forming a substantial portion of the southern crown. Principal branch structure and unions in satisfactory condition. Recent management includes heavy crown reduction back to second order branch structure with virtually all third order branches removed, in additional to this there have been several lower limb removals up to 5 metres above ground level and limb removals of the west crown to accommodate the dwelling that is only a few metres west of the stem. General vitality after pruning is satisfactory with no subsequent decline.	>40	A1	RET
3026	T14	Pedunculate oak	1!	5	9.5	11 :	10.5	12 2.	.5 E	1	1	1660				15.0	0 7	07 M		G	Veteran tree. Very stout lower stem clearly subject to historic pollard management.  Now with a full and healthy regrown crown structure. A tree known to be important to bats. Past management treatment and subsequent regrowth provides habitat features, crevices, decay pockets, water pooling and sap run. Some minor pruning is evident, possibly to remove dead wood or broken limbs. Stable compact crown. Very good overall condition.	>40	А3	RET
3027	А3	Pedunculate oak	2:	2	13	11	10	13.5 2	NE	0.5	1	1480				15.0	0 7	07 M		G	Very stout lower stem. Principal branch structure and unions in satisfactory condition.  Large low limb to north-east and resulting crown bias. Large, broadly spreading and attractive crown form. Good overall condition. High quality landscape tree.	>40	A1	RET
3028		Pedunculate oak	10.	5	7	7.2	7	6 2.	5 W	1	1	740				8.8	8 2	48 M		G	Veteran, relic tree. Only the north-west fragment of the original stem column remains alive amounting to an estimated 20% of the stem circumference of the outermost portion of the former stem. A standing dead section remains at the south-west, this also approximately 20% of the former circumference. The eastern half of the stem has become dead and collapsed to east lying in situ (this should be retained here for habitat/ecological reasons). The former stem size can be approximately determined by measuring across the diameter in a north-south axis (1650mm). The live section currently bears a consolidated but healthy crown. Future management of the crown in the interests of preservation of the stem fragment is sensible and need only amount to periodic peripheral crown reduction pruning work.	>40	A3	RET
3029	А3	Pedunculate oak	2:	1	6.2	7	6	12 3	N	1	1	970				11.6	4 4	25 M		G	Upright stem. Principal branch structure and unions in satisfactory condition. Recent pruning of west crown in the interests of maintenance of the relationship to the proximal dwelling to west. A few pieces of small dead wood remain and may potentially affect third party land.  Remove dead wood >15mm in diameter that may affect adjacent property.	>40	B1	RET

FLAC Ref.	1981 TPO Ref	Species	Ht.	Crow	n Spread	<b>d</b> (m)	Ht. 1 <sup>st</sup>		tem ount	Ster	m Dia. (r	nm)		RPA Rad.	RPA Area	Life Stage	Phys.	Structural condition & Notes Management recommendations	Ret. Spai	QV Grade	Proposal
			(m)	N S	W	,	E (m)	(m)	1 / mea		3	4	5	(m)	(m2)	Y-SM-EM-M-	G-F-P-D		<10, 10+ 20 >40	+, U-A-B-C	
3030	T13	Pedunculate oak	22.5	6 1	0.2	8	7.8 4 S	4	1 150	05				15.00	707	М	F	teran tree. Very stout lower stem. Principal branch structure and unions in isfactory condition. Several small habitat holes throughout scaffold structure. Past ib removal wounds provide for hollowing and habitat spaces. Distal dieback crown renchment and early senescence. Good overall condition.	>40	А3	RET
3031	T1	Pedunculate oak	13	6.3	7.6	7	6.5 4 N	1	1 164	10				15.00	707	М	G	teran tree. Clearly subject to historic pollard management. Very stout lower stem.  and flattening of secondary root development forming a large root plate likely to be aptive growth response to root decay. Cavity from ground level north reveals tensive stem hollowing. Degraded remnant fungal fruiting bracket seen as old achment position on stem burring at 2 metres east, likely <i>Ganoderma</i> species, with oken pieces lying on ground appear to have colouring and spore tube formation ansistent with preliminary identification. Further fungal activity observed as entiporus sulphureus on old branch at 5 metres north in location of either past branch lure or pruning. Multiple and varied habitat spaces through regrown structure seen habitat holes and crevices.	>40	A3	RET
3032	T2	Pedunculate oak	20	8.2	9.2	9.5	9.2 7 N	2	1 175	50				15.00	707	М	G	ry stout lower stem. Burring of lower stem increases diameter. Principal branch ucture and unions in satisfactory condition. Attractive specimen. High quality dscape tree.  No action required at time of survey.	>40	A1	RET
3033	ТЗ	Pedunculate oak	18.4	8.6	9.3	8	9 4.5 W	2	1 117	70				14.04	619	М	G	that stem. Fungal activity observed: <i>Inonotus dryadeus</i> at ground level south (with tatation droplet formation); <i>Fistulina hepatica</i> at 1 metre north. Large scaffold limb m 5 metres west has a decayed section and hollowing close to stem union that may rease the failure potential of the large low limb outboard of the noted defect, uning is advised. Remainder of crown structure is in satisfactory condition.		A1	RET
3034	A1	Scots pine	18.7	6	6.7	6	4.6 8 S	4	1 74	15				8.94	251	М	F	right stem. Typical form and structure for the species. Principal branch structure and long in satisfactory condition.  No action required at time of survey.	>40	B1	RET
3035	A1	Blue Atlas cedar	15.4	9.3	7.4	4.7	10.3 4 E	4	1 74	10				8.88	248	М	F	right stem. Typical form and structure for the species. Principal branch structure and ions in satisfactory condition. Crown bias to east. Foliage appears slightly thinner in normally expected.	20+	B1	RET
3036	A1	Ash	19.5	7.5	8.5	8	9 5 W	4	1 73	30				8.76	241	М	F	right lower stem becomes co-dominant from 2.5 metres with a degree of bark lusion but not significantly hazardous. Several medium sized pieces of dead wood wood >15mm in diameter.	20+	B1	RET
3037	A1	Pedunculate oak	19	11	7.5	10	7.3 4 N	3	1 170	50				15.00	707	М	G	teran tree. Very broad, stout upright stem then becoming a large bole with fully grown crown after cessation of historic pollard management. Cavity from ground el at south-east reveals extensive stem hollowing from within root buttress to an known height within the stem but possibly into the pollard bole. Multiple Laetiporus phureus fruiting brackets observed on old branch removal or branch loss wounds in gion of pollard bole at north and south-west with proximal habitat spaces via browned edecay. Crown structure has previously been reduced, possibly after natural crown renchment but remains in good overall condition both structurally and ysiologically, although the current crown is generally free of smaller sized dead good, broken branches or past storm damage.	>40	A3	RET
3038	A4	Pedunculate oak	15.5	4.8	10	5.8	4.8 2.5 NW	1.5	1 112	20				13.44	567	М	F	put, upright stem. Small cavity between root buttresses from ground level at west. previously severed. Past heavy crown pruning presumably due to presence of eximal dwelling to west. Occasional medium sized dead wood. Satisfactory overall	>40	B1	RET
3039	A4	Ash	12	2	4.8	4.2	4.7 3 S	2.5	1 25	50				3.00	28	EM	F	nder specimen with crown asymmetry due to close companion shelter. Satisfactory erall condition. Tree of relatively low significance.  No action required at time of survey.	>40	B1	RET
3040	A4	Ash	15	5	4	8	2.5 4 W	3	1 39	90				4.68	69	EM	F	ght stem incline to west. Majority of branch structure biased to west. Satisfactory erall condition. Tree of relatively low significance.  No action required at time of survey.	>40	B1	RET
3041	A4	Scots pine	14	2.2	2	5.5	2 8 W	3	1 60	00				7.20	163	EM	F	ght stem incline to north. Compact crown. Satisfactory overall condition. Tree of atively low significance.  No action required at time of survey.	>40	B1	RET
3042	A4	Horse chestnut	15	10	5	3.5	6 2 N	2	1 102	20				12.24	470	М	F	ecimen situated with stem level with north-east corner of proximal residential relling with a companion chestnut to the south. Slight stem incline and general own bias to north. Crown exhibits past itterations of crown pruning and lower imb movals likely to be associated with daylight and proximity issues to the house. Large offold limb form 2 metres north. Prinicpal branch structure and unions in satisfactory and iton.	20+	B1	RET

LAC Ref.	1981 TPO	Species	Tree	Ht.	MRCS	Ht. 1 <sup>s</sup>	t Ht.	Specimen	Specimen			Phys.	Structural condition & Notes	Management recommendations	Ret. Span	QV Grade	Proposal	No. of trees	Trees
No.	Ref	орешес	Count			Br.	Can.	Stem Dia.	RPA Rad.		Y-SM-EM-M-	Conditio G-F-P-D			<10, 10+ 20+,	U-A-B-C		retained	retained
				(m)	(m)	(m)	(m)	(mm)	(m)	(m2)	OM	G-F-P-D	Dispersed linear tree group of small and unremarkable specimens of varying density.	<u> </u>	>40	U-A-B-C			%
G3001		Ash	14	7	4	4 1 N	1	. 200	2.40	1	.8 SM	F	Unremarkable both individually and collectively.	No action required at time of survey.	>40	C2	RET	14	100.0
													Off site tree group. No access. Remote inspection only. Close-set pair share companion shelter, aerodynamic form and a common crown profile. Stems located close to						
													boundary fence. Dense ivy impedes inspection. Principal branch structure and unions						
G3002		Pedunculate oak	2	15	9.5	2.5 W	1	1050	12.60	49	99 M	G	in satisfactory condition. Substantial crown overhang into site. Good overall condition. High quality tree group. Beneath the crown footprint of the two oaks there are	No action required at time of survey.	>40	A2	RET	2	100.0
													additional off site trees along the boundary comprising both conifer and broadleaved						
													species, all significantly smaller in both dimensions and constraints and all of comparative low quality and value.						
													Close-set stems share companion shelter, aerodynamic form and a common crown profile. Trio situated above ice house. Stems and principal branch structures and						
G3003	G2	Sycamore x3	3	19	13	3 2 N	,	1130	13.56	5 57	77 M	G	unions in satisfactory condition. Physiological condition fair for south and north-east	Remove dead wood >20mm in diameter.	20+	B2	RET	2	100.0
03003	GE.	Sycamore x5		13			_	1130	13.50	, ,,,	1		tree but becoming poor for south-west tree seen as thinning of distal branch structure and tip decline and development of small to medium sized dead wood. Hawthorn	Themove dead wood > 2011111111 diameter.	20.	52	1121		100.0
													scrub around base of south-west tree.						
G3004		Sycamore x4, ash x3, hawthorn x2,	25	15.5		5 2 E	1	. 360	4.32		59 EM	F	Cluster of slender upright principal trees comprising ash and sycamore with a scrubby	No action required at time of survey.	>40	C2	REM	0	0.0
		elm x6, elder x3, holly x3		10.0							2		understorey of other species. Quite dense, no management. Low arboricultural merit.	The detail required at time or survey.	1.0		112.01	J	0.0
													A former blackthorn hedge that has now become a line of trees with scrubby understorey after cessation of past hedgerow management. Trees are mostly slender						
													ash, drawn-up after close companion shelter and often multi-stemmed. <i>Inonotus</i>						
		Blackthorn 60%, ash 35%,										_	hispidus decay fungus observed within the dominant ash population likely to result in						
G3005		pedunculate oak 5%	80	19	10	) 2 E	1	. 500	6.00	11	.3 M	F	individual whole and partial tree failures due to the size (diameter) of the trees affected. Positioned internally to the site the tree group has low landscape presence in	No action required at time of survey.	>40	В3	PRET	60	75.0
													comparison with site boundary tree groups. Arboriculturally it is of relatively low merit						
													with only a few distinct trees worthy of individual description as indicated on the plan. Tree count exc. blackthorn						
													Linear tree group along low fence with four Scots pines of larger stem diameter but set						
C2006	A4	Pedunculate oak x3, Scots pine x4,	18	19		7 2 N	1	. 500	6.00	11	.3 M	F	further back from fence to south. Scots pines observed to have a few broken branches	Prune out dead wood and broken branches, the latter including	>40	D2	DET	10	100.0
G3006	A4	ash x10, hawthorn x1	10	19	,	/ Z IN	1	. 500	6.00	11	.5 101	Г	in crowns when viewed from north. Ash often slender and drawn-up after companion	branches hanging in upper north crowns of Scots pines.	>40	B2	RET	18	100.0
													shelter and several are multi-stemmed. Confers some screen function.		-				
G3007	A3	Ash 50%, sycamore, field maple,	50	16	-	7 2 E	2	400	4.80		'2 M	F	Linear tree group on west boundary of site. Often slender, drawn-up ash with scrubby understorey of other species. Although the tree group is comprised of mostly	No action required at time of survey.	>40	B2	RET	50	100.0
03007	713	hawthorn, hazel 50%		10			_	400	4.00		- "		unremarkable individuals collectively they confer useful screen function.	The decision required at time of survey.	740	52	1121		100.0
1													Rather scrubby linear tree group with broad bramble cluster running contiguously						
G3008	A3?	Damson x14, hawthorn x7	20	6	3	3 1 N	1	. 230	2.76	2	.4 M	F	along its length and thicketting to east. Low arboricultural or landscape merit. TPO	No action required at time of survey.	20+	C2	REM	0	0.0
							+						query arises as TPO map unclear; does not merit TPO and probably not included						
G3009		Sycamore x2, ash x2	4	13	6	5 2 S	2	510	6.12	11	.8 M	F	Cluster of specimens in north-west corner of site. Ash at north asymmetrical after suppression by the proximal dominant oak (3030). Includes the off site sycamore at	No action required at time of survey.	20+	B2	RET	4	100.0
													north-west for constraints mapping. Satisfactory overall condition.	,					
G3010		Ash x6, sycamore x3, pedunculate	16	15	,	5 2 N	1	. 350	4.20		5 EM	_	Dispersed linear tree group of varying density. Often scrubby individuals with asymmetry born of companion shelter. Tree group of relatively low arboricultural	No action required at time of survey.	>40	B2	RET	16	100.0
G3010		oak x7	16	15	,	5 Z IN	1	. 330	4.20		DS EIVI	Г	significance.	,	>40	DZ.	KEI	16	100.0
G3011	A1	Leyland cypress	4	10	6.5		0 1	. 600	7.20	16	63 M	F	Close-set linear tree group. Large specimens now displaying typical species weakness o tight but heavy branches resulting in failures at north crown. No recent management	Remove broken and damaged limbs.	20+	C2	RET	4	100.0
G3011	AI	Leyland cypress	4	19	0	'	0 1	. 600	7.20	10	os ivi	Г	evident. Limited future potential Low arboricultural merit.	nemove broken and damaged iimbs.	20+	C2	KEI	4	100.0
		Norway spruce x1, Lawson cypress											Cluster of unremarkable specimens. Norway spruce is larger than the mean dimensions with a stem diameter estimated to be 250+250mm, a height of 11 metres and crown						
G3012	A1?	x1, Lawson cypress cv x1, ash x1	4	6	3	3	0 0	200	2.40	1	.8 EM	F	radius of 4 metres. All unremarkable both individually and collectively. TPO query as	No action required at time of survey.	20+	C2	RET	4	100.0
													may be too young to have been present in 1981  Close-set trio of similar sized specimens share companion shelter, aerodynamic form						
G3013	A1	Red horse chestnut	3	11	6.8	8 6 W	3	480	5.76	10	)4 EM	F	and common crown profile. Some typical bark dysfunction but otherwise in satisfactory overall condition.	No action required at time of survey.	20+	B2	RET	3	100.0
							1						Tree group represents the northernmost trees of the wider tree group (continuing to						
C201 4	TC204.4	Holm ook		4.0	٠.	4.57	3-		7.00		11 84		south) for constraints mapping. Diameter recorded here represents the specimen 6.8	No action required at tiref	. 40	D2	DET	_	100.0
G3014	163014	Holm oak	3	16	8.5	5 4 N	2.5	650	7.80	19	91 M	G	metres to east of the existing manhole, one tree is closer but quite a bit smaller.  Typical form and structure for the species albeit some crown asymmetry due to	No action required at time of survey.	>40	B2	RET	3	100.0
							1						companion shelter. Satisfactory overall condition.						
		Scots pine		18.6		5.5 W		730	8.76	24	1 M	_	Close-set pair share companion shelter. Both trees have suffered past limb failures but	No action required at time of survey.	20+	B2	RET	2	100.0

FLAC Ref. No.	1981 TP	Species	Tree Count	Ht.	MRCS	Ht. 1 <sup>s</sup>		Specimen Stem Dia.	•	Specimen	Life Stage	Phys. Condition	Structural condition & Notes	Management recommendations	Ret. Span	QV Grade	Proposal	No. of trees retained	Trees retained
				(m)	(m)	(m)	(m)	(mm)	(m)	(m2)	Y-SM-EM-M- OM	G-F-P-D			<10, 10+ 20+, >40	U-A-B-C			%
													Close-set pair share companion shelter and aerodynamic form. Principal branch						
TG3016	A4	Ash	2	25	11	1 6 E	2.5	885	10.62	354	M	F	structure and unions in satisfactory condition. Occasional medium sized dead wood.	Remove dead wood >20mm in diameter.	>40	A2	RET	2	100.0
													Satisfactory overall condition.						

# Data for hedges (H)

FLAC Ref. No.	Species	Ht.	Mean Width	Length	Mean Stem Dia.	Life Stage	Phys. Condition	Structural condition & Notes	Management recommendations	Ret. Span	QV Grade	Proposal
		(m)	(m)	(m)	(mm)	Y-SM-EM-M- OM	G-F-P-D			<10, 10+ 20+, >40	U-A-B-C	
H3001	Leyland cypress	3	3	22	230	М	- E	Ownership uncertain, potentially an off site item. Specimens have been heavily topped. Low arboricultural merit.	No action required at time of survey.	20+	C2	RET
H3002	Leyland cypress, cherry laurel	2.5	1	32	120	EM	G	Off site hedge. Regularly clipped. Good overall condition.	No action required at time of survey.	>40	B2	RET
Н3003	Hawthorn, holly	2.5	1	85	120	EM	F	Off site hedge. Regularly clipped. Some variation in density beneath principal trees. Good overall condition.	No action required at time of survey.	>40	B2	RET
H3004	Cherry laurel	2.2	1	65	120	М	G	Off site hedge. Regularly clipped. Good overall condition.	No action required at time of survey.	>40	B2	RET



# Recognition of Ancient, Veteran & Notable Trees – R A V E N

# Step One—Size Assessment

# Tree has very large girth for species

Note—pollarding & senescence reduce stem increment: girth may be deceptive – assess stem girth relationship with life-stage accordingly

Refer to Ancient and other veteran trees: further guidance on management (Lonsdale, ATF 2013) at Fig. 1.3: Chart of girth in relation to age and developmental classification of trees

IF GIRTH NOT VERY LARGE FOR SPECIES, STOP HERE!

Step T	wo—Additional Primary Features
At leas	t one of the following should be present, or refer to Step Three
	Extensive decay, especially brown rot or exposed stem heartwood in relevant species
	Extensive hollowing
	Crown senescence
	Retrenchment
Step T	hree—Secondary Features
If no ac	dditional Primary Feature is present, tree should have at least four Secondary Features
	Large quantity of dead wood in crown, especially where large-sized
	Major storm damage/ breakout wounds
	Habitat spaces: decay holes and/ or crevices/ branch splits sheltered from direct rainfall
	Aerial rooting
	Sap run/ slime flux
	Water pool
	Bark loss inc. due to lightning strike
	Fungi
	Other epiphytic plants, including significant presence of lichens
Step F	our – Identification Guide
	ANCIENT
	Veteran tree with extremely large girth: age likely > 50% of estimated species maximum E.g. pedunculate oak, 2m stem dia, average site: ca. 460 years old, ca. 50% of species max
	VETERAN
	Very large girth for species and qualifies under either Step Two or Step Three
	NOTABLE
	Very large girth for species but does not qualify under either Step Two or Step Three

IF A TARGET IS PRESENT, ASSESS RISK USING THREATS





# Guide to column headings

Tree No. Refer to accompanying plan

Species Listed by common name

Form Key factors that influence significance of stem size and age

Form Key factors that influence significance of stem size and age estimation

Pollard Whether the tree bears a pollard form, even if now long grown out

Relic Tree assessed as bearing <75% of former maximum crown volume

Required primary feature
Additional primary features
Secondary features
Extensive decay
Exposed HW

Tree must be large relative to others of its kind to qualify for assessment; refer to Lonsdale 2013

Features of principal importance for identifying A/V trees. In each case, feature should be present significantly Less important though still valuable features that aid identification, especially where present in numbers Exposed decay areas should exceed 400cm2

HW refers to heartwood; applicable to relevant species only

DW>150mm dia
Maj. Storm damage
Dry habitat space
Water pool
Signif. bark loss/ LS
Notable fungi
Other epiphytic plants

Dead wood present in the crown, with diameter over 150mm
Breakout wounds or broken spars exceeding 30cm dia
Potential for faunal use where not subject to rain entry
Offers niche habitat for specialist inverts, even where transient
Bark loss exceeding 400cm2. LS refers to lightning strike
Refers to species with known associations to old-growth trees
Should be either rare or present in significant quantity

Age estimate Computed using FC White Method, form & senescence weighting added

Ancient Veteran trees beyond ca. 50% of species' maximum life expectancy

Material & Reimann on Secondary footures as listed.

Veteran Trees with Required & Primary or Secondary features as listed


Notable Trees that are large and/ or becoming old for species, but which lack qualifying features


Non-special All other trees

Note - Stem dia. for 3028 reflects estimated former maximum, used here for dating purposes; current dia. 740mm

Tree no.	Species	Form REQUIRED PRIMARY FEATURE			Either: ADDITIONAL PRIMARY FEATURES - at least one of							Or: SECONDARY FEATURES - at least four of												STIMATE		RAVEN AS	SSESSMENT		NOTES
		Pollard	d Relic Large stem dia.		Extensive decay		′	Hollowing	Senescence	Retrenchment	DW>150mm dia	Maj. Storm Damage	Dry habitat space	Aerial roots	Sap run/ slime flux	Water pool	Signif. bark loss/ LS	Fungi		Other epiphytic plants			Years	Origin	Ancient	Veteran	Notable	Non-special	
				(mm)	Brown rot	Exposed HW	Other											Notable Of	ner	Lichens	Ferns	Other							
3007	Pedunculate oak		х	1450			Х	х	х	Х	х	Х	Х				х		(				325	1694		Х			
3008	Pedunculate oak			1130																			181	1838			Х		Just qualifies by size & age, but lacks veteran features
3010	Pedunculate oak			930																			138	1881				Х	Meets none of the criteria for veteran status
3014	Pedunculate oak			980		х							Х				Х						148	1871			Х		Some veteran features present but size & age insufficient to merit veteran descriptor
3015	Pedunculate oak			1460							Х												268	1751			Х		Qualifies by size & age, but lacks sufficient veteran features for descriptor to apply
3018	Pedunculate oak	Х		1760	Х			Х		Х	Х	Х	Х					Х					427	1592	Х				Laetiporus sulphureus & Fistulina hepatica present
3021	Ash		Х	1520	Х	х		Х	Х			Х	Х	Х			Х	х					354	1665	Х				Fungi not identifed due to absence of fruitbodies, but brown rot very unusual on ash
3022	Pedunculate oak			1205																			200	1819			Х		Just qualifies by size & age, but lacks veteran features
3023	Pedunculate oak			1365								Х											242	1777			Х		Qualifies by size & age, but lacks sufficient veteran features for descriptor to apply
3025	Pedunculate oak			1460																			268	1751			Х		Just qualifies by size & age, but lacks veteran features
3026	Pedunculate oak	Х		1660			Х						Х		Х	Х							392	1627		Х			Approaching ancient status
3027	Pedunculate oak			1480																			274	1745			Х		Just qualifies by size & age, but lacks veteran features
3028	Pedunculate oak		Х	1650		х		Х	Х	х	х		Х										389	1630		Х			Approaching ancient status
3030	Pedunculate oak			1505				Х	Х	х			Х										314	1705		Х			
3031	Pedunculate oak	х		1640				Х		х			Х					х					386	1633		Х			Approaching ancient status. L.sulpureus & G.resinaceum likely present
3037	Pedunculate oak	х		1760	Х			Х					Х					х					427	1592	Х				Laetiporus sulphureus present

2





avoid contamination of the rooting area

trees ('high-risk operation'), and requires on-site arboricultural supervision by FLAC

**OUTLINE ARBORICULTURAL MANAGEMENT PLAN** 

within the constraints of best practice and the controlling statutory protection

Tree risk and general management It is acknowledged at (a) above that reasonable measures

in the interests of sound arboricultural management

Best practice and legislative control It is acknowledged at (b) above that statutory tree

e. Preparation of documentation appropriate for submission to CBC's Trees Section in pursuit of consent to undertake works to trees under statutory

tree protection, as necessary

# Veteran tree management

The cohort of veteran trees by virtue of their age, size and condition confer attributes of exceptional biodiversity, cultural or heritage value. Maintaining these attributes is a primary objective of the management plan, sitting alongside the general objectives listed above.

consultant at the start of an operation; supervision will be carried out to ensure that the method statement is understood and complied with.

17. No mechanical excavation including lowering of levels shall occur within the RPA.

18. Excavations of the top 600mm associated with any construction activities within the RPA shall be carried out carefully and by hand tools only e.g. spades, shovels, trowels etc, this may include a hand held pneumatic breaker where sub-surface structures are encountered and their removal is essential. Air excavation tools may be employed where operatives have an understanding of the use of these tools in proximity to roots and soil conditions allow. Care must be taken to avoid damage to the bark of parts of roots that will be retained.

E) ROOT TREATMENT

19. Root pruning operations may proceed only under arboricultural supervision.

20. Typically, where roots are encountered they are first assessed primarily for size; roots over 25mm in diameter should be retained (or referred for further arboricultural advice) and those below 25mm in diameter should be pruned at 90 degrees to the direction of the root.

21. Proprietary cutting tools only shall be used to prune roots i.e. secateurs and sharp pruning saws.

22. Should any roots over 25mm be discovered they should only be severed following consultation with the arboricultural consultant with regard to the tree's health and stability.

23. Where roots are to be left exposed for any period of time they shall be protected from the drying effect of wind and sunlight, e.g. wrapped in clean dry Hessian to prevent desiccation.

24. Prior to backfilling retained roots should be unwrapped and surrounded by sharp sand (not builder's sand because of the high salt content which is toxic to tree roots) or another loose granular material before

soil is replaced. 25. Any imported topsoil for backfilling must be of good quality and free of contaminants and foreign bodies, it must be well graded and friable to promote good growing conditions and perform as a suitable rooting medium. The topsoil to be used must satisfy the

requirements of a multipurpose topsoil as is described

within BS3882:2007.

26. All materials, including any new topsoil to replace the hard surface must be close to hand prior to commencement of the works. These works will be carried out to the recommendations of BS5837: 2012 7.2 (see below). Once the works are complete tree protection fence is to be erected around the new open

F) ARBORICULTURAL SUPERVISION & REPORTING

28. All high risk operations (i.e. intra-RPA /VTB) require arboricultural supervision. Additionally ongoing inspection of the tree protection measures shall be provided whilst works are in progress. A schedule of supervision is provided elsewhere on this drawing.

A WRITTEN & PHOTOGRAPHIC REPORT WILL BE PROVIDED WITHIN 5 WORKING DAYS OF EACH MONITORING VISIT

The tree stock site wide shall require management in the interests of both trees and users of the surrounding land 1,1 h. both on and off site. The overarching objectives are as i.

Discharge duty of care obligations owed to residents, visitors and neighbours imposed by both common law and Owners and Occupiers Liability Act

Preserve and enhance arboricultural attributes

The second bullet at (b) captures all trees within the site but this necessarily includes a subset of veteran trees that shall require specific considerations (see sub-heading *Veteran tree management* below)

must be taken to minimize the risk of tree failures resulting in harm or damage. This shall be achieved by cyclical tree inspections to provide:

works recommendations as deemed necessary to achieve an acceptable level of risk d. A schedule of ancillary works if considered advisable

protection is in force and accordingly tree management requires adherence to legislative controls affecting tree works ordinarily by application to Cheltenham Borough Council for consent, this shall be achieved by:

Inspection cycles, qualifications and review The first inspection shall take place immediately prior to first occupancy

Heads of terms for management of veteran trees

g. Condition and maintenance of veteran tree

of works schedule for application to CBC

interests of optimizing habitat

radius knee-rail

deterrent planting

of veteran trees

f. Condition and maintenance of veteran tree crown

Maintenance of land within veteran tree buffers

Arboricultural risk-facing inspection and preparation

Assessment of veteran attributes (i.e. structural and

conditional features of ecological potential - please

refer to RAVEN) including works advisable in the

Assessment of works advisable in the interests of

mechanical failures and preserving the oldest parts

preservation, for example to prevent major

m. The period between inspections as described above shall be every two years

Inspections shall be undertaken by suitably qualified, trained and experienced arboriculturists (i.e. ideally qualified to level 6) with reference to suitable ecologists as appropriate. At each inspection a detailed works specification shall be prepared as

Tree work shall be undertaken by qualified and experienced arboricultural contractors and they shall be briefed by the project arboriculturist prior to commencing works

p. Tree work shall be undertaken in accordance with BS3998:2010 Tree work - recommendations. Care shall be taken to ensure that nesting birds and bats are not disturbed, and that bat roosts are not damaged during tree work. Pre-work surveys for bats shall be undertaken in accordance with BS8596:2015 Surveying for bats in trees and woodland - Guide

q. Cycles of inspection provide an opportunity to review the management plan particularly in light of tree condition and emerging information relating to tree management.